



**MOTORCYCLING
AUSTRALIA**

Memorandum

To: **File:**
Date: Monday 24th September 2007 **Doc No:**
From: **cc:**
Re:

We have become aware of problems causing fuel leakage or the dislodging of the fuel cap on some 2006 and 2007 KTM motorcycles. New fuel caps for these motorcycles are awaiting clearance from customs.

KTM Australia is working cooperatively with Motorcycling Australia to resolve this issue.

It is essential Scrutineers inspect and carefully check the fuel caps on all 2006 and 2007 KTM machines to ensure the caps are adequately sealed and firmly located into the tank to prevent possible dislodgement.

It is strongly recommended in the interim that on all KTM machines the fuel cap is secured with duct tape.

All owners of 2006 and 2007 KTM machines should contact their relevant dealer/supplier.

enjoy the ride

abn 83 057 830 083

P.O. Box 134
147 Montague St
South Melbourne
Victoria 3205
Australia

t: 03 9684 0500
f: 03 9684 0555
e: mail@ma.org.au
w: www.ma.org.au

International
t: +61 3 9684 0500
f: +61 3 9684 0555

The controlling body
of motorcycle sport in
Australia affiliated to
the Federation
Internationale de
Motocyclisme [F.I.M]



Supported by



Australian Government
Australian Sports Commission